

How to clean and care for the finish on your **coping and fascia**



To ensure that the factory-applied, heat-cured painted finish on your edge metal retains its original beauty, these highly durable finishes should be cleaned occasionally.

Here's how:

- 1** Use mild soap solutions that are safe for use with your bare hands such as those products that one would use to wash a car.
- 2** Avoid the use of strong acid or alkali cleaners as they may damage the finish.
- 3** Remove grease, sealants, or other materials with a solvent no stronger than mineral spirits or denatured alcohol.
NOTE: Never mix cleaners or cleaners and solvents as the resultant mixture can cause harmful or even dangerous results. Do not use abrasive cleaners or materials such as steel wool or abrasive brushes, which can also harm the surface.
- 4** Once heavy soil, grease, or sealant has been removed, apply a mild soap solution with a soft cloth, sponge, or soft brush. Rinse the surface thoroughly with clean water and dry with a soft cloth.

In coastal areas where the finish is exposed to salt spray, or in areas with heavy industrial pollutants, clean the finish regularly, for example, when you clean your building's windows.



Visit **gaf.com**

For additional information, contact GAF Design Services
at 1-877-423-7663 or designservices@gaf.com

We protect what matters most™

