



The Public Health and Safety Organization

NSF Product and Service Listings

These NSF Official Listings are current as of **Thursday, December 02, 2021** at 12:15 a.m. Eastern Time. Please [contact NSF](#) to confirm the status of any Listing, report errors, or make suggestions.

Alert: NSF is concerned about fraudulent downloading and manipulation of website text. Always confirm this information by clicking on the below link for the most accurate information:

<http://info.nsf.org/Certified/Protocols/Listings.asp?Company=78140&Standard=P151&>

NSF P151 Health Effects from Rainwater Catchment System Components

GAF

1 Campus Drive
Parsippany, NJ 07054
United States
800-766-3411

Facility : Walpole, MA

Rooftop Coatings[1]

TOPCOAT® Membrane WOB
TOPCOAT® Flashing - Brush Grade WOB
United Coatings™ Roof Mate WOB Flashing
United Coatings™ Roof Mate WOB Coating
WOB Acrylic TopCoat®
WOB Brush-Grade Acrylic Flashing

[1] Number of Coats: 2

Maximum Field Use Dry Film Thickness (in mils): 16 wet mils per coat

Recoat Cure Time and Temperature: 24 hours at 75°F

Final Cure Time and Temperature: 48 days at 75°F

Colors: White

Facility : Gainesville, TX

Rooftop Liners[1]

EverGuard Extreme® TPO

[1] Certified for the following thicknesses: 50, 60, 70, and 80 mils. Certified for the white colored liner only.

Number of matching Manufacturers is 1

Number of matching Products is 7

Processing time was 0 seconds